

FOR INFORMATION ONLY

DISHWASHER ERROR CODE E8 - ALTERNATIVE VALVE

E8 – Defective alternate valve functioning

This error code is generated when the dishwasher programme starts and the appliance does not detect a signal from the alternative valve saying that the alternative valve is correctly positioned. This defect can be caused by, but not only, a defective alternate valve.

The alternative valve is a component that distributes water between the upper and lower spray arms within the dishwasher. The advantage of this is that less water is required for each wash.

The alternative valve is located in the base of the appliance and is sometimes referred to as a diverter valve or alternate valve.



An example of an alternative valve