


SERVICE BULLETIN

VERSION	00	First version
Document n°	LVS-SB2014-01-00- clutch kit for built-in models	
Brand	SMEG	
Models involved	All built-in models series 820h and 860h	
Cause	Functional improvement	
Modification description	The original clutch has been replaced with a new component whose configuration has been updated (<i>kit p/n 690072859</i>). The new component is with free wheel which allows a better sliding.	
Introduction date	20/01/2014	
Interchangeability	yes	


NEW CLUTCH APPLICATION



1-Remove the cord.



SERVICE BULLETIN



... Be careful that the cord end does not interfere with the sliding wheel.