



**ELECTROLUX HOME PRODUCTS PTY LTD**  
ABN 51 004 762 341

**Technical Bulletin N° REB284**

**Issue: 1**  
**Date: 6/10**

**WEB SITE ADDRESS: [www.partnship.com.au](http://www.partnship.com.au)**

## **Water Tube Repair Kit**

**Models Affected:**      **All SXS Ice & Water models**

**Problem:**

The water supply hose splits or breaks off in or near the bottom of the freezer door, rendering it unrepairable and a replacement door would be required

**Field Fix:**

Use kit ES6063 to thread a replacement hose through the existing hose and use supplied adaptor to reconnect to existing supply hose.

**Note:**

1. The hose is smaller and will reduce water flow by about 15%
2. This will negate the need for a replacement door and save the cost of a door to the consumer
3. Ensure lines are pushed fully into all connectors
4. Always check for leaks after the installation of this kit

## Ice Water Supply Tube Replacement Procedure

1. Cut off old tube ensuring a straight neat edge close to door panel (remove any burs)



2. Insert protective sleeve (about 12 cm) over new tube supplied 1.8m length ( use a piece of old hose for this purpose) this is only for added protection.



3. Insert the tube up through old hose into door until it is seen at water spout exit



4. Attach the adaptor supplied and join to existing the hose from the water valve



5. Push into place and secure hose under cabinet

6. Cut off any excess at tube supply exit

