


SERVICE BULLETIN

Date	22/03/01
Document n°	FRN - SB2001-01 - Oven commutator
Last Doc. n°	-----
Brand	Smeg
Appliances involved	Built-in ovens : SE108X/1, SA392EB/1, SE392MFB1, SE392MF/1
Parts code	-----

Problem	-----
Cause	-----
Modification description	For the above mentioned models the commutator code 811730130 has been superseded by the code 811730201, for few serial numbers. See the drawing below for the wiring connection.
Solution	-----
Date of introduction	The code 811730201 has been fitted on the oven SE108X/1: from serial number 07109317 to 07109416 SA392EB/1: from s.n. 08102323 to 08102372 SE392MFB1: from s.n. 08111417 to 08111466 from s.n. 11117118 to 11117166 SE392MF/1: from s.n. 11117168 to 11117201
Interchangeability	There is interchangeability.



V	purple
M	brown
C	blue
B	white
R	red
N	black
G	grey